

65290

**OFF-SITE SAMPLE RESULTS**  
**PCBs ANALYSIS**

# ENVIRONMETRICS

2345 Millpark Drive  
Maryland Heights, MO 63043-3529  
(314) 427-0550

RIEDEL ENVIRONMENTAL SERVICES  
500 EASTERN AVENUE  
BENSONVILLE, IL 60106

ATTN: MARK DOUGLAS

INVOICE # 31702  
PROJECT # 8168 - SAUGET, SITE G

## ANALYSIS REPORT

PCBs IN SOIL

SW-846 8080

<u>LAB NO.</u>	<u>SAMPLE NO.</u>	<u>IDENTIFICATION</u>	<u>TOTAL ppm</u>	<u>TYPE</u>
9504/275-001		OS-DA 4/17/95 13:00	<3	--
9504/275-001 MATRIX SPIKE		OS-DA 4/17/95 13:00	41 81 %RECOVERY	1248
9504/275-002		OS-1 4/19/95 12:30	5	1260
9504/275-003		OS-2 4/17/95 13:00	<3	--
METHOD BLANK		PCB 3432	<2	--

DATE RECEIVED : 4/19/95 9:04  
DATE ANALYZED : 4/24-24/95  
ANALYST : C.D.

APRIL 25, 1995

  
WAYNE L. COOPER  
LABORATORY DIRECTOR